

24 HOUR GENERATION CHECKLIST Approved For Release **BX6859** : CIA-RDP89B00041R00180905001227 SEC 131

| ITEM | TASKS REQUIRED | H-HOUR START | H-HOUR COMP | ACTUAL TIME COMP | TIME COMP | | CP CALLED | |
|------|--|--|----------------|------------------------|-----------|------|-----------|------|
| | | | | | PRI | SEC | PRI | SEC |
| 1 | MAINTENANCE ALERTED | | H-24 | 1000 | | | | |
| 2 | DCM MEETING | | H-23 | 1100 | | | | |
| 3 | MAINT SECURE NITROGEN, OXYGEN | | H-23 | 1100 | | | | |
| 4 | PCL SECURE TRUCKS | | H-23 | 1100 | | | | |
| 5 | START MISSION AIRCRAFT PREFLIGHT | H-22:30 | H-00:30 | 0930 | | | | |
| 6 | RECEIVE FUEL LOAD FROM FLIGHT PLANNING | | H-22:30 | 1230 | | | | |
| 7 | | | H-22 | 1200 | | | | |
| 8 | TEB AND REFUEL 25X1 | H-22 | H-19 | 1500 | 1400 | 1315 | 1415 | 1315 |
| 9 | ARC-50 CODES RECEIVED | | H-22 | 1200 | | | | |
| 10 | COMMO AND IFF PREFLIGHT | H-22 | H-18 | 1600 | 1000 | 1200 | | |
| 11 | SELECT RECOVERY CREW AND GIVE TO DCM | H-20 | H-16 | 1800 | | | | |
| 12 | INS PREFLIGHT | H-18 | H-16 | 1800 | 1245 | 1230 | 1300 | 1240 |
| 13 | | H-16 | H-13 | 2100 | 1445 | 1745 | 1445 | 1800 |
| 14 | PACKAGE DATA RECEIVED | | H-13:45 | 2145 | | | | |
| 15 | PACKAGE LOADED (CALL SECURITY BEFORE MOVING PACKAGE) | H-13 | H-08:30 | 0130 | 2200 | 2225 | 2210 | 2250 |
| 16 | | H-13 | H-08:30 | 0130 | 2200 | 2225 | | |
| 17 | | | H-10:45 | 2315 | | | | |
| 18 | LOX TOP OFF | H-4 | H-03:30 | 0630 | 0130 | 0430 | | |
| 19 | NITROGEN TOP OFF | H-4 | H-03:30 | 0630 | 0030 | 0500 | | |
| 20 | AIRCRAFT STATUS BRIEF: CC, INS, 25X1 | H-03:30 | H-3 | 0700 | | | | |
| 21 | START INS WARMUP | | H-03:30 | 0630 | 0630 | 0700 | 0635 | 0715 |
| 22 | INSTALL OSC MAGAZINE IN NOSE | H-03:30 | H-3 | 0700 | 0800 | | | |
| 23 | INS DATA TAPE LOADING | H-02:30 | H-2 | 0800 | | | | |
| 24 | PACKAGE I HELIUM PURGE Q-BAY | H-2 | H-00:30 | 0930 | | | | |
| 25 | PERSONAL EQUIPMENT LOADED | H-02:15 | H-2 | 0800 | | | | |
| 26 | MAINT CALL SECURITY TO STERLIZE COCKPIT | H-2 | H-01:50 | 0830 | | | | |
| 27 | COCKPIT SET UP PER CODE SHEET | | H-01:50 | 0810 | | | | |
| 28 | VIEWFINDER LOADED WITH FILM | Approved For Release 2003/01/24 : CIA-RDP89B00041R001809050021-2 | | H-01:30 | H-1 | 0900 | | |
| 29 | ENGINEER CHECK AIRCRAFT | | | | | | | |

Approved For Release 2003/01/24 : CIA-RDP60B00041R001800050021-2

SEC

| ITEM | TASKS REQUIRED | H-HOUR START | H-HOUR COMP | ACTUAL TIME COMP | TIME COMP | | C.P. CALLED | |
|------|--|-----------------|----------------|------------------------|-----------|-----|-------------|-----|
| | | | | | PRI | SEC | PRI | SEC |
| 30 | ENGINE START | | | H-00:30 | 0930 | | | |
| 31 | TAXI | | | H-00:20 | 0940 | | | |
| 32 | RECOVERY GEAR IN PLACE | | | H+1 | 1100 | | | |
| | | | | | | | | |
| | | | | | | | | |
| | POST MISSION LANDING CHECKLIST | | | | | | | |
| | | | | | | | | |
| 1 | LAND AND COOL AIRCRAFT | | | L+00:00 | L+00:30 | | | |
| 2 | SECURE ACFT AND SERVICE ENG OIL | | | L+00:30 | L+01:15 | | | |
| 3 | | 25X1 | | L+00:30 | L+01:15 | | | |
| 4 | REMOVE VIEWFINDER, FILM STRIP AND MAPS | | | L+00:30 | L+01:15 | | | |
| 5 | | 25X1 | | L+00:30 | L+01:15 | | | |
| 6 | MAINTENANCE DEBRIEF | | | L+00:45 | L+01:15 | | | |
| 7 | REMOVE INSTRUMENTATION PACKAGE | | | L+01:00 | L+01:15 | | | |
| 8 | MOVE ARTICLE INTO HANGAR | | | L+01:15 | L+01:30 | | | |
| 9 | DOWNLOAD PKG (NOTIFY SECURITY TO CLOSE HANGAR DOORS) | | | L+01:30 | L+02:30 | | | |
| 10 | | 25X1 | | | L+03:30 | | | |
| 11 | | | | | L+04:15 | | | |
| 12 | "TAKE" TO SUPPLY (NOTIFY SECURITY BEFORE MOVING TO SUPPLY) | | | | L+05:00 | | | |
| 13 | | | | | L+05:00 | | | |
| 14 | | 25X1 | | | L+05:00 | | | |
| 15 | | | | | L+05:00 | | | |
| 16 | | | | | L+09:00 | | | |
| 17 | | | | | L+10:00 | | | |